TANGARATTA STOCKFEEDS PTY LIMITED

771 WALLAMORE ROAD, WALLAMORE NSW 2340 **EPL 2775**

NOISE COMPLIANCE MONITORING FEBRUARY 2017

Report received: 1 March 2017 Attended monitoring: 14-18 February 2017

Licence Condition L2.1

Noise generated from the premises must not exceed the noise limits in the table below.

| Locality and Location | Day LAeq (15 min) | Evening LAeq (15 min) | Night LAeq (15 min) | Night LA1 (1 min) |
|---|----------------------|--------------------------|------------------------|----------------------|
| Location 1: Nearest affected residence known as "Rosebank" located at Lot 22 in DP.733610 on Wallamore Road, Tamworth | 38 | 37 | 35 | 45 |
| Location 2: Any other affected residence | 38 | 37 | 35 | 45 |



Licence Condition M4.1

Compliance outlined above

Table 1: Measured Noise Levels February 2017

| | D (| 1.4 | 14 100 1 1 1 1 1 1 | | | | |
|------------|------------|------------|----------------------------------|---------------------|---------------------|--|--|
| Time | Date | L1 | L90 | Leq | Audible Noise | | |
| DAY | | | | | | | |
| 14:00 | 14/02/17 | 54.0 | 36.7 | 43.8 | 4,6,12,1 | | |
| | L90 = 35.7 | Tangaratta | Tangaratta Leq = <38 # | | Tangaratta L1 = N/A | | |
| 11:45 | 15/02/17 | 54.1 | 35.8 | 44.0 | 6,12,1,9 | | |
| Tangaratta | L90 = <36 | Tangaratta | Tangaratta Leq = <38 # | | Tangaratta L1 = N/A | | |
| 12:45 | 16/02/17 | 57.5 | 36.1 | 51.1 | 7,4,12,6,1 | | |
| Tangaratta | L90 = <35 | Tangaratta | Tangaratta Leq = 37 | | Tangaratta L1 = N/A | | |
| EVENING | | | | | | | |
| 19:15 | 14/02/17 | 66.2 | 33.4 | 50.8 | 7,6,10,3 | | |
| Tangaratta | L90 = 34 | Tangaratta | Tangaratta Leq = 37 | | Tangaratta L1 = N/A | | |
| 18:45 | 15/02/17 | 58.3 | 35.2 | 45.8 | 6,9,1 | | |
| Tangaratta | L90 = 35 | Tangaratta | Tangaratta Leq = 36 | | Tangaratta L1 = N/A | | |
| 20:30 | 16/02/17 | 55.7 | 35.1 | 45.1 | 6,4,1,10 | | |
| Tangaratta | L90 = 35 | Tangaratta | Tangaratta Leq = 37.0 Tangaratta | | jaratta L1 = N/A | | |
| NIGHT | | | | | | | |
| 02:00 | 15/02/17 | 53.5 | 33.9 | 40.5 | 6,9,2,1 | | |
| Tangaratta | L90 = 34 | Tangaratta | Tangaratta Leq = 35.0 | | Tangaratta L1 = <45 | | |
| 01:00 | 16/02/17 | 50.8 | 34.6 | 40.8 | 2,11,7 | | |
| Tangaratta | L90 = <34 | Tangaratta | Tangaratta Leq = 34 | | Tangaratta L1 = <45 | | |
| 00:15 | 17/02/17 | 51.6 | 35.5 | 38.7 | 15,8,7,2 | | |
| Tangaratta | L90 = 34 | Tangaratta | a Leq = 35.5 | Tangaratta L1 = <45 | | | |

<u>Criteria</u>: Day = 38dB(A),Leq (15min), Evening = 37dB(A),Leq (15min), Night = 35dB(A),Leq (15min) & 45dB(A),L1 (15min), # Difficult to confirm due to extraneous noise contributions.

Legend of Noise sources:

Tangaratta mill
Insect, frogs, etc
Truck leaving rear of mill
Cars Wallamore Rd
Truck Wallamore Rd
Irrigation pump
Activities at dairy
Rosebank mill
Aeroplane
Insect, frogs, etc
Cars Wallamore Rd
Activities at dairy
Rosebank mill
Wind on mic

DISCUSSION AND CONCLUSION

Results of our attended noise surveys confirm that noise emissions from the Tangaratta site are compliant with the criteria during the evening and night at the Rosebank residence. Only estimates of noise contributions from the Tangaratta site were possible during the day, as the mill at the rear of the Rosebank residence dominated the acoustic environment. In saying this, our observations do confirm that the Tangaratta plant was operating below the criteria during the day.